United States Post Office 524 Main Street Columbus Lowndes County Mississippi

HABS MISS, 44-colum, 23-

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Atlanta, Georgia 30303

d States Department of the Interior Service lington, D.C. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICA BUILDINGS SURVEY

ARCHITECTURAL OATA FORM

HAB5 MISS, .

44-colum, 23-

VAILE 1	COUNTY	IDWN OK VICINILT	
Mississippi	Lowndes	Columbus	
HISTORIC NAME OF STRUCTURE (NCLUCE SOURCE FOR NAME)	<u> </u>	HABS NO.
United States Post Office (Fr Columbus, Mississippi	om Original Building Plans)		MS-214
SECONDARY OR COMMON NAMES OF	STRUCTURE		
None			
COMPLETE ADDRESS (DESCRIBE LO	CATION FOR RURAL SITES)	·	
524 Main Street, Columbus, MS	39701	•	
DATE OF CONSTRUCTION (INCLUDE Begin 1938 (Date of Dec. 27,1 ginal plans. Date of 1938 on Completed 1939 (This date on pl SIGNIFICANCE (ARCHITECTURAL A		CLUDE SOURCE) own, Architect (Froinal building plans INAL USE OF STRUC	s).
Has been a United States Post Office from date of construction until present.			
has been a united states fost utilide from date of construction until present.			
			·
STYLE (IF APPROPRIATE) Modified Georgian			
MATERIAL OF CONSTRUCTION (INC Exterior - Brick with white s floor, marble wainscot, plast	LUDE STRUCTURAL SYSTEMS) tone trim. Pitched roof - co er. Structure - steel and r	pper. Interior los einforced concrete	oby - marble
HAPE AND DIMENSIONS OF STRUC	TURE (SKETCHED FLODR PLANS	DN SEPARATE PAGES	ARE ACCEPTABLE)
Print of main floor plan and photographs of elevations included. Complete set of original plans, including floor plans, are on file in subject Post Office			
EXTERIOR FEATURES OF NOTE			
White entry with 24" white columns against background of dark brick. White cupola against dark copper roof.			
· · · · · · · · · · · · · · · · · · ·	per 1001.		
INTERIOR FEATURES OF NOTE (DE	SCRIBE FLOOR PLANS IF NOT	SKETCHED)	
Marble floors and marble wainscot in lobby.			
Mural across one end of lobby	•		
		•	
MAJOR ALTERATIONS AND ADDITION None to date	NS WITH DATES		
Hone to date		·	
		······	
PRESENT CONDITION AND USE General condition good. Small	l repairs needed. Presently	used as U. S. Pos	t Office.
OTHER INFORMATION AS APPROPRI	ATE		**************************************
See National Register nomination for further details on physical description, historical information about mural and building of Post Office.			
SOURCES OF INFORMATION (INCLU- Nominated for listing on Natio in national park service in Wa	onal Register and approved b	v state of Mississ	TERS, ETC.) ippi. Presently

COMPILER, AFFILIATION U. S. Postal Service Field Real Estate & Buildings Office

DATE

8/6/80